ENGINE 119.97 as of 1.6.91

BT07.41-P-0001-01A	LH-SFI variable reference resistor modified	⊯ BT

Standard production breakpoints/Modifications/New features

Engine	LHS	Transm	Engine	Engine	Productio	Productio	Nature and reason for modification	Reference/Remarks
	RHS	ission	end no.	end no.	n period	n period		
			as of	up to	as of	up to		
119.97					01.06.91			

As of 06/91 color-coded variable reference resistors have been installed. Models:

- with TWC green variable reference resistor
- without TWC white variable reference resistor

(USA/California version does not have a variable reference resistor)

On models with TWC and national version it is **not** permitted to install a white variable reference resitor otherwise the secondary air injection pump will run constantly and the air pump may be damaged as a result.