AF42.10-U-1100BG	Whistling/howling noise from front brakes - when not applied! Frequency can be	
	affected by actuating brakes or moving steering wheel	

MODEL 124.036 #B up to 930495 with CODE (491) U.S. version MODEL 124.036 #B up to 927761

Damage code	Cause	Remedy	
	Friction vibration	1 Adjust wheel bearing play.	ra33001240300x
		Caution!	
		Adjust wheel bearing play to 1/100 mm.	
		↓	
		If adjustment is not successful	
		↓	
42 111 36		2 Replace fixed caliper on front axle left	ra42001240110x
		and right.	
		Notes	
		Install parts according to parts ordering note	
		table.	
		An entry in the registration papers is not	
		necessary.	
		Brake hose installation:	
		Ensure that wheels have clearance to brake	
		hose when turned to left lock and vehicle	
		suspension compressed.	
		Defending the selection of a second second second	
		Before installation clarify cost assumption with	
		ESCULAB or fax inquiry indicating damage code.	

Parts ordering notes

Part no.	Designation	Quantity
129 420 00 83	Fixed caliper (left)	1
129 420 01 83	Fixed caliper (right)	1