## Replacement Keys Are Not Available

129, 140, 163: GP 80.57

## **EXPLANATION:**

The global team continues to work on this. Unfortunately there have not been any updates since NCU posting in August. What makes this different than other supply constraints is there is no active vendor for these parts so it's a much larger exercise for Daimler to identify and establish production capability with another supplier.

## **ACTION:**

- Reference NCU for applicable part numbers
- Our global teams are leveraging every effort to provide a new solution, and we will communicate to everyone as soon as a solution is available

**NOTE:** Valet transponder keys for the 98-05 163's are available.

## Replacement Keys Are Not Available

